

Course Name

Supervise Asbestos Removal



Course / qualification / unit code and title

(CPCCB4051A Supervise asbestos removal)

Course overview

Course overview

The course covers the part 4.3 of the WHS/OHS Regulations and meets the needs of removal personnel and supervisors to competently remove asbestos.

Prerequisites / entry requirements

In order to commence this skill set participants are required to have completed the pre-requisite unit:

- CPCCWHS1001 - Prepare to work safely in the construction industry (or equivalent)
- CPCCE3014A Remove non-friable asbestos and/or
- CPCCE3015A Remove friable asbestos

Structure and Duration

Course Structure

Four hour program to cover part 4.3 of the WHS/OHS Regulations and meets the needs of removal personnel and supervisors to competently remove asbestos.

Course duration

4 hours.

Outcomes and Recognition

Course outcomes

The course provides skills and abilities to act as supervisor leading a licensed asbestos removal team.

Recognition

On successful completion of this course, the participants will be awarded a Statement of Attainment for the unit. In addition learners will be provided with an industry Blue Card.

Licensing and registration information

Licensing requirements vary based on whether the State or Territory has accepted the WHS harmonised legislation. For States that operate under this legislation, then an individual will require the units of this course to be able to conduct Asbestos removal and or supervision. Note: The organisation for which the individual works must also must be registered the relevant work safe.

For States that have not adopted the WHS harmonised legislation (e.g. Victoria), Worksafe require *the organisation to be licensed* and to use trained operatives (who have attend a course at an approved training organisation) – PICAC is approved by Worksafe Victoria.

Delivery and assessment

Delivery arrangements

The course is delivered over a half-day at the PICAC campus.

Training for this course will be conducted at the PICAC campus or other approved and suitable location. The PICAC facility has a purpose built practical training area for the Asbestos classes. Subject to timetabling and minimum student numbers, this program can be delivered either during the:

- **daytime** for candidates required to complete skills development required for in house training by employers or
- **daytime or evening** for self-employed or unsponsored employees wishing to advance their skills.

The program involves both classroom delivery and practical demonstrations and practice. The classroom will on the supervisory and regulatory requirements for the safe removal of ACMs.

Assessment arrangements

Assessments are designed to verify that you are competent in the supervision of safely removing ACMs. To confirm that you are competent you will be observed demonstrating and role-playing your skills. In addition, you will need to complete written questions.

Recognition of Prior Learning (RPL)

As this course is conducted primarily as a Worksafe Victoria or similar assured program, recognition of prior learning may not be offered. It is unlikely that RPL would be granted on experience alone and that a demonstration of skills and the application of knowledge will be required to meet regulatory requirements.

Applications for RPL may be considered where there is clear justification – in which case candidates will be required to complete all assessments identified here.

Please contact PICAC if you are considering RPL to discuss.

Fees

Fees, charges and eligibility

Category A – Training participant is a “fully financial” PPTEU member. May be registered in training course by self or employer.

Category B – Training participant is a Master Plumbers, AMCA or NFIA Association member.

Category C – Training participant is not a member of PPTEU, Master Plumbers, AMCA or NFIA.

Fees summary

	Category A	Category B	Category C
Asbestos Supervision	\$0	\$160	\$200